

CONTENTS

Introduction

More Secret Car Warranties in
Lemon-Aid 1

Part One

BUYING A NEW VEHICLE 3

More Choice, Better Deals 3
Buying Tips 5
Which New Car, Truck, SUV,
or Van? 8
When and Where to Buy 11
Frivolous Freight Charges 14
Buying the Right Car or Truck 14
Safety 16
The Test Drive 22
Seniors and Driving 23
Making Driving Accessible 32
Highway High-Tech 35
When “New” Isn’t New 38
Fuel Economy Fantasies 41
Saving on Service 49
“Hidden” Costs 51
Negotiating the Options Jungle 54
Paying a Fair Price 70
Leasing Fleecing: Why Leasing
Costs More 75
Trade-In Tips 83

Part Two

OLD WHEELS AND GOOD DEALS 87

Buying Used Is the Popular Choice 87
Make Defects Harder to Hide 89
Parts Can Be Cheaper for a Used
Vehicle 92
When and Where to Buy 95
Don’t Pay Too Little 98
Financing Choices 104
Dealer Tricks 106
Private Scams 109
Auto Insurance 111
Helpful Websites 113
Summary 117

Part Three

THE ART OF COMPLAINING 119

It Pays to Complain 119
Two Warranties 122
Supplementary Warranty Scams 124
Supreme Court Tackles “Fine Print” 125
Broken Promises 128
Negligence 129
Reasonable Durability 130
Strategies for Successful
Complaining 132
Using Government Agencies 139
Secret Warranties and Special
Programs 139

Part Four

2007-2018 RATINGS “GOOD CARS, BAD CARS” 145

How *Lemon-Aid* Picks the “Best” and
“Worst” 145

Terms Used in Part Four 147

American Models 155

American Car Quality 155

Fiat Chrysler and Jeep 156

FIAT CHRYSLER AUTOMOBILES 162

JEEP 197

FORD 216

GENERAL MOTORS 270

Japanese and Korean Automakers 332

ACURA 332

HONDA 345

HYUNDAI 375

INFINITI 397

KIA 406

LEXUS 426

MAZDA 437

MITSUBISHI 457

NISSAN 467

SUBARU 506

SUZUKI 521

TOYOTA 526

European Vehicles 565

Luxury Lemons 565

AUDI 566

BMW 588

MERCEDES-BENZ 606

MINI 624

VOLKSWAGEN 630

VOLVO 652

MODEL INDEX 661

KEY DOCUMENTS

Introduction

- 2010-15 Subaru CVT Warranty Extension 1
- 2011-15 Subaru Enhanced Warranty Coverage for Engine Oil Consumption Concerns 2

Part One

BUYING A NEW VEHICLE 3

- 2018 Models 4
- 2007-2010 – Nissan – CVT customer satisfaction program 7
- Good “Senior” Car Choices 28
- Vehicles with Class-Leading Fuel Consumption 43
- Winter Tire Recommendations 60

Part Two

OLD WHEELS AND GOOD DEALS 87

- Bill of Sale 96
- Average Auto Premium by Province 112

Part Three

THE ART OF COMPLAINING 119

- Reasonable Part Durability 130
- 2006-13 Honda – Civic paint chalking, cracking, or cloudy 131
- 2011-15 Chevrolet Caprice and 2012-15 Chevrolet Impala – special coverage adjustment – engine cooling fan motor 131
- Complaint Letters – samples 134
- Secret Warranty Roundup 140

Part Four

2007-2018 RATINGS “GOOD CARS, BAD CARS” 145

- Rustproofing 153

American Models

- TIPM Units Faulty on Various Chrysler Products 189
- Chrysler – fuel spit back 190
- Doors that Won’t Latch 217
- A Canada-Wide Class Action Settlement May Affect Your Rights 222
- 2011-14 Ford – excessive transmission clutch shudder and/or automatic transmission fluid leak 226
- 2008-11 Ford – paint degradation/road abrasion 231
- 2011-14 Ford – rear axle vent – oil leak 242
- 2009-11 Ford – transmission – slip/neutral out – 5th gear start from stop – backup camera on in drive 256
- 2011-2015 Ford – A/C – exhaust odor in cabin 259
- 2011-2014 Ford – excessive oil consumption, smoke from the exhaust 261
- Aluminum Panels 265
- 2011-14 Ford – delayed engagement park to forward or reverse 268
- 2014 GM – defective camshaft position oil control valve 271
- 2005-13 GM – airbag light 272
- 2013-16 GM – engine wiring harness chafing 272
- 2008-15 GM – “sag or hesitation” on acceleration – normal 283

- 2012-14 GM – excessive oil consumption – oil leaks – blue exhaust smoke – MIL – or fuel trim codes 284
- 2013 GM – steering clunk no power assist 285
- 2014 GM – wet carpet on driver’s side 286
- 2010-14 GM – power steering stick-slip 292
- 2013-14 GM – bearing damaged or engine will not rotate 292
- 2014 GM – 2-3 upshift or 3-2 downshift clunk noise 296
- 2014 GM – tail lamp gasket seal 297
- 2007-13 Cadillac – clunk noise after shifting from reverse to drive or drive to reverse and then accelerating 301
- 2010-15 GM – steering shudder (vibration) during slow speed maneuvers 314
- 2012-13 Cadillac – crankshaft rear oil seal – oil leaks 317
- 2007-14 GM – engine oil consumption on aluminum block/iron block engines with active fuel management 323
- 2015-2016 GM – engine cylinder head gasket leak 324
- 2013 GM – flex fuel sensor malfunction 330
- 2014 GM – shift lever contacts ignition key 331

Japanese and Korean Automakers

- Excessive Vibration in CR-V 360
- 2008-12 Honda – high oil consumption – faulty engine rings 364

- Kia – steering/suspension – pull or drift concern 425
- 2007-14 Lexus – HVAC evaporator drain hose clogged due to insect intrusion 436
- Nissan Doubles CVT Warranty 468
- 2007-12 Nissan – engine – oil leak from upper end of oil cooler 475
- 2007-12 Nissan – brake master cylinder 483
- Nissan – rear suspension member, bushing replacement 486
- 2009 Nissan – L/H rear suspension knuckle 489
- 2014 Nissan – campaign #PC311 to replace engine on/off push button 494
- 2003-12 Nissan – grinding/knocking noise from rear on turns 494
- 2010-12 Nissan – navigation system – screen goes blank 498
- A Reliable Supplier for Rebuilt 2.5L Subaru Engines 506
- “Boxed” by Subaru 510
- 2013-14 Subaru – engine oil consumption 511
- 2010-15 Subaru – CVT warranty extension 515
- 2003-09 Toyota – smart stop technology 527

European Vehicles

- 2007-15 Audi – electrical – harness damage from animal bites 577
- Tech Tip – 2012-15 BMW Models 588
- Mercedes-Benz – Defective Gears Cost Big Money 608
- Volkswagen – Diesel 630
- 2011-12 Volkswagen – intake manifold & fuel injectors 639